

OSU SPEARS SCHOOL OF BUSINESS BUILDING



OKLAHOMA STATE UNIVERSITY

AUGUST PROGRESS REPORT

8.31.2017



MONTHLY OVERVIEW

- ♦ START INSTALLING CARPET TILES ON 4TH FLOOR
- ♦ INSTALLATION OF VANITIES AND SINKS
- ♦ INSTALL WOOD CEILINGS IN LENORMAN CLASSROOM
- ♦ CONT. GFRC INSTALLATION

- ♦ STARTED WALL VINYL ON 2ND FLOOR
- ♦ CONT. INSTALL OF EXTERIOR DOORS
- ♦ POLISH TERRAZZO ON 2ND FLOOR
- ♦ CONT. EXTERIOR CONCRETE
- ♦ CONT. INSTALLATION OF FRAMING FOR ELEVATED DECKS

MONTHLY PROGRESS REPORT

PROGRESS REPORT: THIS AUGUST, THE EXTERIOR OF THE PROJECT SITE CONTINUES TO PROGRESS WITH SIDEWALKS, LIGHT POLE BASES BEING POURED ON THE NORTH AND EAST SIDES, AS WELL AS GRADING FOR THE NEW PARKING LOT ON THE EAST SIDE. WE HAVE INSTALLED THE GEO-FOAM AND GRAVEL ON THE PLAZA DECK IN PREPARATION FOR PAVERS. WE HAVE RECEIVED ALMOST ALL OF THE GFRC EXCEPT FOR A FEW REMAKES TO GET CLOSER TO COMPLETION OF THE GFRC. WE HAVE BEEN INSTALLING EXTERIOR DOORS AND FRAMES AT THE ENTRANCES THAT ARE STILL OPEN. TERRAZZO HAS BEEN POLISHED ON THE SECOND FLOOR AND IS STARTING TO BE POURED ON THE FIRST FLOOR. THE BASEMENT CLASSROOMS HAVE STARTED TO BE DECKED AS WELL AS THE LENORMAN RISERS BEING CONSTRUCTED.

AS CONSTRUCTION CONTINUES, MANHATTAN WILL ISSUE MONTHLY PROGRESS REPORTS THROUGHOUT THE CONSTRUCTION PROCESS. TYPICALLY, THESE REPORTS ARE GENERATED AND TRANSMITTED ON THE LAST DAY OF EACH MONTH. THESE REPORTS ARE MEANT TO SERVE AS A TOOL FOR OSU LONG RANGE FACILITIES PLANNING TO DOCUMENT PRODUCTION AND KEEP INTERESTED PARTIES UPDATED WITH PROGRESS WHOM WOULD NOT OTHERWISE BE INVOLVED ON A DAILY BASIS.



CEILINGS







PICTURED ABOVE:

2ND FLOOR SAMPLE CLASSROOM

PICTURED LEFT:

3RD FLOOR K FIXTURES INSTALLED

PICTURED BOTTOM LEFT:

BASEMENT LENORMAN CLASSROOM WOOD SLAT CEILING



EXTERIOR IMPROVEMENTS



PICTURED ABOVE:

EXTERIOR NE SITE GRADING

PICTURED RIGHT:

PLAZA PLANTER BED BRICK

PICTURED BELOW:

PLAZA FOAM AND DRAINAGE







EXTERIOR IMPROVEMENTS



PICTURED ABOVE:

SOUTH SIDE SIDEWALK FORMWORK

PICTURED RIGHT:

SOUTH SIDE SIDEWALK POURED

PICTURED BELOW:

EAST SIDE SITE GRADING







INTERIOR FRAMING, AND FINISHES







PICTURED ABOVE:

PAINTED BASEMENT COLUMN

PICTURED LEFT:

3RD FLOOR BATHROOM SINKS AND **FAUCETS**

PICTURED BELOW LEFT:

SAMPLE CLASSROOM BACKLIT COLUMN



FLOORING



PICTURED ABOVE:

2ND FLOOR TERRAZZO POLISHED

PICTURED RIGHT:

4TH FLOOR INSTALLED CARPET

PICTURED BELOW:

3RD FLOOR CARPET MOISTURE Barrier







AERIAL PHOTOS



AUGUST 2017







APRIL 2015

May 2015

JUNE 2015







JULY 2015

AUGUST 2015

SEPTEMBER 2015







OCTOBER 2015 NOVEMBER 2015 DECEMBER 2015



AERIAL PHOTOS







JANUARY 2016

FEBRUARY 2016

MARCH 2016







APRIL 2016

May 2016

JUNE 2016







JULY 2016

AUGUST 2016

SEPTEMBER 2016







OCTOBER 2016

NOVEMBER 2016

DECEMBER 2016







JANUARY 2017 FEBRUARY 2017

March 2017



AERIAL PHOTOS








APRIL 2017 MAY 2017 JUNE 2017







July 2017 August 2017 September 2017







OCTOBER 2017 NOVEMBER 2017 DECEMBER 2017



JANUARY 2018



"The only thing better than recognizing a quality product is building one."

www.manhattanconstruction.com



UPCOMING ACTIVITIES FOR SEPTEMBER

- ♦ CONT. CARPET AND LVT INSTALL ON 2ND FLOOR
- ♦ START WALL VINYL IN BASEMENT
- ♦ BEGIN PLAZA PAVERS
- **♦** CONT. GFRC INSTALLATION
- ♦ START DROPPING CEILING TILES IN THE BASEMENT
- ♦ CONT. POURING TERRAZZO ON FIRST FLOOR
- **♦** CONT. EXTERIOR CONCRETE
- **♦** CONT. EXTERIOR CIVIL GRADING

FOR A LIVE FEED OF THE PROJECT, VISIT:

HTTP://SPEARS.OKSTATE.EDU/BUILDING/LIVE/

HTTP://SPEARS.OKSTATE.EDU/BUILDING/



DETERMAN SCHEIRMAN, INC. CONSULTING ENGINEERS



Oklahoma State University, Long Range Facilities Planning,

