

OSU SPEARS SCHOOL OF BUSINESS BUILDING



OKLAHOMA STATE UNIVERSITY

JULY PROGRESS REPORT

7.31.2016



MONTHLY OVERVIEW

- ♦ CONT. EXTERIOR WALL FRAMING
- ♦ CONT. BASEMENT DUCTWORK/PLUMBING
- ♦ CONT. SHEATHING AND WEATHER BARRIER
- ♦ CONT. INSTALLING BRICK MASONRY

- ♦ SET THE FIRST DORMERS
- ♦ CONT. ROOF FRAMING, DECKING AND DETAIL
- ♦ TAPPED 24 INCH CHILLED WATER LINES
- ♦ STARTED INTERIOR WALL LAYOUT IN THE BASEMENT
- ♦ PLAZA AND 1ST FLOOR LOGGIA SOMD WERE POURED

MONTHLY PROGRESS REPORT

PROGRESS REPORT: THIS JULY, THE PLAZA AND 1ST FLOOR LOGGIA SOMD WERE POURED ALONG WITH SOME EQUIPMENT PADS LOCATED ON THE NORTH AND SOUTH ENDS ON THE 1ST, 2ND, 3RD, AND 4TH FLOORS. EXTERIOR WALL FRAMING CONTINUES ON THE INTERIOR RADIUS OF THE BUILDING. SHEATHING AND WEATHER BARRIER ARE NEARING COMPLETION ON THE EXTERIOR RADIUS AND HAVE BEGAN ON THE INTERIOR RADIUS. INTERIOR WALL LAYOUT HAS BEGUN AND BRICK MASONRY IS MAKING GROUND AROUND THE BUILDING, TOUCHING THE SECOND FLOOR ON THE SOUTH SIDE AND BROUGHT UP TO SCAFFOLD HEIGHT ON THE NORTH AND EAST SIDES. ROOF FRAMING, DECKING AND DETAIL IS BEING INSTALLED AND THE FIRST DORMER HAS BEEN SET IN PLACE. MEP BASEMENT ROUGHIN IS UNDERWAY AND STEEL ERECTION IS NARROWING DOWN TO ITS FINAL DAYS.

AS CONSTRUCTION CONTINUES, MANHATTAN WILL ISSUE MONTHLY PROGRESS REPORTS THROUGHOUT THE CONSTRUCTION PROCESS. TYPICALLY, THESE REPORTS ARE GENERATED AND TRANSMITTED ON THE LAST DAY OF EACH MONTH. THESE REPORTS ARE MEANT TO SERVE AS A TOOL FOR OSU LONG RANGE FACILITIES PLANNING TO DOCUMENT PRODUCTION AND KEEP INTERESTED PARTIES UPDATED WITH PROGRESS WHOM WOULD NOT OTHERWISE BE INVOLVED ON A DAILY BASIS.

MANHATTAN IS PROUD TO PARTNER WITH OSU LONG RANGE FACILITIES PLANNING, SPEARS SCHOOL OF BUSINESS, AND ELLIOT AND ASSOCIATES ON THIS PROJECT.



1 ST DORMER FLY, ROOF FRAMING & DECKING



PICTURED ABOVE:

PLACEMENT OF THE FIRST **DORMER**

PICTURED LEFT & BELOW:

ROOF FRAMING, DECKING AND DETAIL





FRAMING, SHEATHING, & WEATHER BARRIER



PICTURED ABOVE & RIGHT: WEATHER BARRIER, SHEATHING, AND FRAMING ALONG THE NORTH AND EAST EXTERIOR WALLS

PICTURED BELOW: SHEATHING AND FRAMING ON THE SOUTH SIDE **INTERIOR RADIUS**










PICTURED ABOVE:

EAST BRICK MASONRY

PICTURED RIGHT:


SOUTH BRICK MASONRY

PICTURED BELOW:






SOMD CONCRETE POURS






BASEMENT DUCTWORK



PICTURED:

DUCTWORK **INSTALLATION IN THE BASEMENT**





AERIAL PHOTO



JULY 2016







APRIL 2015

May 2015

JUNE 2015







July 2015

AUGUST 2015

SEPTEMBER 2015







OCTOBER 2015 NOVEMBER 2015


DECEMBER 2015

March 2017



JANUARY 2017

AERIAL PHOTO



FEBRUARY 2017



"The only thing better than recognizing a quality product is building one."

www.manhattanconstruction.com



UPCOMING ACTIVITIES FOR JULY

- CONT. BASEMENT DUCTWORK AND RISERS
- CONT. EXTERIOR WALL FRAMING
- CONT. EXTERIOR WALL SHEATHING ON INTERIOR AND EXTERIOR **RADIUS**
- CONT. WEATHER BARRIER ON EXTERIOR WALLS ON INTERIOR AND **EXTERIOR RADIUS**
- CONT. BRICK MASONRY
- CONT. ROOF FRAMING, DECKING AND DETAIL
- CONT. SETTING DORMERS
- CONT. LAYING OUT BASEMENT, 2ND, 3RD, AND 4TH FLOOR WALLS

FOR A LIVE FEED OF THE PROJECT, VISIT:

HTTP://SPEARS.OKSTATE.EDU/BUILDING/LIVE/

HTTP://SPEARS.OKSTATE.EDU/BUILDING/



DETERMAN SCHEIRMAN, INC. CONSULTING ENGINEERS



Oklahoma State University, Long Range Facilities Planning,

