

OSU SPEARS SCHOOL OF BUSINESS BUILDING



OKLAHOMA STATE UNIVERSITY

JUNE PROGRESS REPORT

6.30.2016



MONTHLY OVERVIEW

- CONT. EXTERIOR WALL FRAMING
- STARTED INSTALLING THE PLAZA DECKING
- STARTED BASEMENT DUCTWORK/PLUMBING
- CONT. SHEATHING AND WEATHER BARRIER
- Installed the Metal decking for the 2nd floor loggia Balcony
- POURED THE 3RD AND 4TH FLOOR NORTH SOMDS, THE 2ND FLOOR LOGGIA BALCONY, AND 2ND & 3RD FLOOR BALCONIES
- ERECTED THE LOGGIA AND PLAZA STRUCTURAL STEEL
- STARTED INSTALLING BRICK MASONRY

MONTHLY PROGRESS REPORT

PROGRESS REPORT: THIS JUNE, THE 3RD & 4TH FLOOR NORTH SOMDS WERE POURED ALONG WITH THE 1ST FLOOR EAST VESTIBULE SOG, 2ND & 3RD FLOOR BALCONIES, & 2ND FLOOR LOGGIA BALCONY. INSTALLATION OF DUCTWORK IN THE BASEMENT HAS BEGUN & STRUCTURAL STEEL ERECTION CONTINUES. EXTERIOR WALL FRAMING CONTINUES & IS COMPLETE FROM THE 1ST-3RD FLOOR ON A/Z LINE. SHEATHING AND WEATHER BARRIER HAS BEEN COMPLETED ON THE SOUTH SIDE OF THE BUILDING UP TO THE EAST VESTIBULE & BRICK MASONRY HAS STARTED.

AS CONSTRUCTION CONTINUES, MANHATTAN WILL ISSUE MONTHLY PROGRESS REPORTS THROUGHOUT THE CONSTRUCTION PROCESS. TYPICALLY, THESE REPORTS ARE GENERATED AND TRANSMITTED ON THE LAST DAY OF EACH MONTH. THESE REPORTS ARE MEANT TO SERVE AS A TOOL FOR OSU LONG RANGE FACILITIES PLANNING TO DOCUMENT PRODUCTION AND KEEP INTERESTED PARTIES UPDATED WITH PROGRESS WHOM WOULD NOT OTHERWISE BE INVOLVED ON A DAILY BASIS.

MANHATTAN IS PROUD TO PARTNER WITH OSU LONG RANGE FACILITIES PLANNING, SPEARS SCHOOL OF BUSINESS, AND ELLIOT AND ASSOCIATES ON THIS PROJECT.



EXTERIOR FRAMING, SHEATHING, & WEATHER **BARRIER**



PICTURED:


NEWLY INSTALLED EX-TERIOR FRAMING, SHEATHING, AND WEATHER BARRIER ON THE SOUTH & EAST SIDES OF THE NEW BUILDING








LOGGIA/PLAZA STEEL ERECTION & **DECKING**




PICTURED:

STEEL ERECTION AND METAL DECKING PRO-**GRESS THROUGHOUT** THE JUNE ON THE Loggia & Plaza





SOMD CONCRETE POURS





BRICK MASONRY & BASEMENT PLUMBING/ **DUCTWORK**



PICTURED ABOVE:

THE START OF BRICK MASONRY ALONG THE SOUTH WALL

PICTURED RIGHT & BE-LOW:

DUCTWORK & PLUMBING ROUGH-IN IN THE BASE-





AERIAL PHOTO



JUNE 2016







APRIL 2015

May 2015

JUNE 2015







JULY 2015

AUGUST 2015

SEPTEMBER 2015








OCTOBER 2015 NOVEMBER 2015 DECEMBER 2015



JANUARY 2017

AERIAL PHOTO




FEBRUARY 2017

March 2017



"The only thing better than recognizing a quality product is building one."

www.manhattanconstruction.com



UPCOMING ACTIVITIES FOR JULY

- START 1ST FLOOR PLAZA AND LOGGIA FRAMING
- CONT. BASEMENT DUCTWORK AND RISERS
- CONT. EXTERIOR WALL FRAMING
- CONT. EXTERIOR WALL SHEATHING AND BEGINNING INSIDE RADI-US
- CONT. WEATHER BARRIER ON EXTERIOR WALLS AND BEGINNING INTERIOR RADIUS
- CONT. BRICK MASONRY
- START ROOF FRAMING, DECKING AND DETAIL
- CONT. FRAMING AND INSTALLING WOOD GUTTER TROUGHS

FOR A LIVE FEED OF THE PROJECT, VISIT:

HTTP://SPEARS.OKSTATE.EDU/BUILDING/LIVE/

HTTP://SPEARS.OKSTATE.EDU/BUILDING/



DETERMAN SCHEIRMAN, INC. CONSULTING ENGINEERS



Oklahoma State University, Long Range Facilities Planning,

